

New documents released by Chairman Waxman identify “critical” and “major” deficiencies in the construction of the new U.S. Embassy in Baghdad, raising questions about the decision of the State Department to certify in December that the Embassy compound was “substantially complete.”

Documents and Links

- [Letter to Secretary of State Condoleezza Rice](#)
- [Review of Sprinkler System](#)
- [Review of Fire Water Supply System](#)
- [Review of Notifier Fire Alarm Systems](#)
- [Review of Kitchen Suppression Systems](#)
- [Overseas Building Operations Inspection Report](#)